



# service bulletin

TO: SERVICE MANAGER  TECHNICIANS   
PARTS MANAGER

**No. 95-18**

## Hino Diesel-Excessive Black Smoke

### Models

Hino W06DTI-II 310 HP Inboard Engines

### Situation

The above model engines may emit excessive black smoke at cruise speed and/or at full load rated speed (WOT).

### Correction

Replace the original two-piece exhaust with the new one-piece design. The new elbow is available in a kit which includes necessary hardware for installation. The elbow replacement is Quicksilver Part Number 807475 A2.

### Warranty

Fill out warranty claim and send it to your normal warranty processing center. More than one engine can be put on the warranty claim if you list the part number, engine model, serial number, warranty code and labor hours for each engine on separate lines on warranty claim.

Warranty Code and Labor:

R&R Exhaust Elbow	EXCP	2.5 Hours
-------------------	------	-----------

Old parts should be scrapped. Do not return the old parts with the claim.