

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

25/30 EFI FourStroke Outboard Product ECM Ground

Models Affected

Models Covered	Serial Number
Mercury/Mariner 25/30 EFI Outboard Electric Start Models	0R125005 and above


NOTE: This service bulletin only pertains to electric start engines. Manual start versions are not affected.

Situation

Some of the models above may experience a poor running condition due to an inconsistent ECM ground path. These engines may not start, misfire, run for a period of time and stall, flicker the oil light, display incorrect RPM data in CDS, or any combination of these.

Correction

To alleviate the inconsistent ground path, install a jumper wire from the ECM/battery cable ground bolt located on the starter housing to the bolt securing the solenoid plate to the cylinder block.



- a - Solenoid plate mounting bolt
- b - ECM/battery cable ground bolt
- c - Added ground wire

43435

Parts Required

Qty.	Description	Part Number
1	Cable assembly	88807A19

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Warranty

Mercury Marine will credit the dealer for the cost of parts and labor.

Complete the warranty claim listing:

- Outboard serial number
- 0.5 hour labor
- Warranty flat rate code: SB05
- Qty. 1, cable assembly (88807A19)
- Part code: 361
- Fail code: 00

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.