

TO: SERVICE MANAGER TECHNICIANS
PARTS MANAGER

No. 96-2

Water In Fuel Module (WIF) Warning Light

Models

MCM/MIE D7.3L/270 Diesel Engines


Situation

The warning light on the Engine System Monitor Panel may not operate correctly.

Correction


Change wire on WIF light on Engine System Monitor Panel as shown.

Current Wiring Set Up



72432

Correct Wiring Set Up



72432