



service bulletin

No. 97-12

Emissions Notification for 300 Pro Max/Super Magnum (3.0L)

LETTER TO OWNERS & DEALER INVENTORY

The attached letter and a replacement decal are being sent to registered owners of Hi-Performance 300 Pro Max/Super Magnum outboards. The letter instructs the owner to replace the EPA Certification Decal. All 1998 engines in dealer inventory below serial number 0G703352 (with the exception of the engines listed below) will need the revised decal installed before sale.

Engines before S/N 0G703352 that had the correct decal installed at the factory:

0G503409	0G703051	0G703189 thru 0G703193
0G610049	0G703107 thru 0G703110	0G703204 thru 0G703206
0G610233	0G703123 thru 0G703127	0G703232 thru 0G703234
0G610433	0G703160	0G703237
0G610496 thru 0G610498	0G703163	0G703245
0G703029 thru 0G703031	0G703168	0G703253
0G703039	0G703176	0G703352
0G703050	0G703177	

WHAT TO DO

Send a fax to Mercury Hi-Performance service with a serial number list of 300 Pro Max/Super Magnum outboards in your inventory and we will mail you the required replacement decals

We appreciate your cooperation. The EPA requires the certification decal to be accurate.

Hi-Performance Fax No: 920-924-2096

MERCURY[®]

HI-PERFORMANCE

N7480 COUNTY "UU"
FOND DU LAC, WI 54935
PHONE (920) 921-5330
FAX (920) 929-5060

A BRUNSWICK COMPANY

Dear Owner:

Our records indicate you own a Mercury or Mariner Hi-Performance outboard that may have an EPA (Environmental Protection Agency) certification decal that contains inaccurate information. Enclosed, you will find a revised decal. Please install this new decal over the original which is located on the flywheel protection cover underneath the top cowl (refer to your Operation & Maintenance Manual for top cowl removal procedure).

We apologize for this inconvenience and sincerely appreciate your cooperation.

Sincerely,
Mercury Hi-Performance

A handwritten signature in black ink, appearing to read "Dave Christie". The signature is fluid and cursive, with a large initial "D" and a long horizontal stroke at the end.

Dave Christie
Director, MHP Service