

120 and 125 HP Parts Book Error

The printed Parts Book and the Microfiche parts books for the 1989, 90 and 91 model year 120 and 125 HP engines has an error on the powerhead page.

The thermostat, illustration number 88, on the Powerhead page reads 528068 130°. This is incorrect, it should read 664068 130°. Please make this change in your parts books and retain this bulletin for handy reference.