



parts bulletin



No. 95-7

FORCE OUTBOARD AND SPORT JET MODELS

STATOR AND REV LIMITER CHART

HP	MODEL & MODEL YEAR	ORIGINAL STATOR	SUPERSEDED TO	REQUIRES
40/50 FORCE	1992C To 1994-1/2 S/N E000001 Thru E065560	398-818535A14	398-9710A47	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065561 Thru E138599	398-818535A14	398-9710A47	Does Not Need Voltage Regulator Change
70 FORCE	1991B To 1994-1/2 S/N E000001 Thru E065371	398-8778A10 or 398-8778A26	398-9873A35	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065372 Thru E138599	398-8778A29	398-9873A32 or 398-9873A35	Does Not Need Voltage Regulator Change
90 FORCE	1991H To 1994-1/2 S/N E000001 Thru E065504	398-8778A10 or 398-8778A26	398-9873A35	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065505 Thru E138599	398-8778A29	398-9873A32 or 398-9873A35	Does Not Need Voltage Regulator Change
120 FORCE	1991D To 1994-1/2 S/N E000001 Thru E065486	398-8778A23	398-9710A45	Needs 815279T5 Voltage Regulator
	1994-1/2 To 1995 S/N E065487 Thru E138599	398-8778A27	398-9710A45	Does Not Need Voltage Regulator Change

90 SPORT JET	1993 S/N E009600 Thru E031401	398-8778A10	398-9873A35	Needs 815279T5 Voltage Regulator and 821889A36 Rev Limiter
	1993 To 1994-1/2 S/N E031402 Thru E067404	398-8778A10	398-9873A35	Needs 815279T5 Voltage Regulator
	1994-1/2 S/N E067405 Thru E095087	398-8778A29	398-9873A32 or 398-9873A35	Does Not Need Voltage Regulator or Rev Limiter Change
120 SPORT JET	1995 S/N E095088 Thru E141088	398-818535A14	398-9710A47	Needs 821889A36 Rev Limiter